

# “Cosmics” Data December 2005

G.Gaycken

Laboratoire Leprince-Ringuet - Polytechnique

Calice ECAL Meeting, 6 March 2006

# Outline

- 1 Summary of cosmics run  
January 2006
- 2 First results of cosmics run  
February 2006

# Cosmics Test Setup

- Cosmics Test December 2005/January 2006:
  - 16 ECAL Layers on top of 4 HCAL layers.
  - Regulator boards for low voltage lines.
  - New low voltage power supplies.
  - Slow control for power supplies.

# Cosmics Test Setup

- **Cosmics Test December 2005/January 2006:**
  - 16 ECAL Layers on top of 4 HCAL layers.
  - Regulator boards for low voltage lines.
  - New low voltage power supplies.
  - Slow control for power supplies.

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
    - bugs/features in DAQ control program
  - Leakage current raised above threshold for  $\sim 1$  PCB (which?)
    - slow control switched ECAL off after a few days.
  - One new PCB was not connected
    - (was considered to be responsible for high leakage currents.)
  - Two PCBs connected to broken FEs.

Due to these problems: data of limited use!

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0$  V
    - mostly pedestal data.
  - Leakage current raised above threshold for  $\sim 1$  PCB (which?)
    - slow control switched ECAL off after a few days.
  - One new PCB was not connected
    - (was considered to be responsible for high leakage currents.)
  - Two PCBs connected to broken FEs.

Due to these problems: data of limited use!

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0$  V
    - mostly pedestal data.
- Leakage current raised above threshold for  $\sim 1$  PCB (which?)
  - slow control switched ECAL off after a few days.
- One new PCB was not connected
  - (was considered to be responsible for high leakage currents.)
- Two PCBs connected to broken FEs.

Due to these problems: data of limited use!

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0V$ .
    - mostly pedestal data.
- Leakage current raised above threshold for  $\sim 1$  PCB (which?)
  - slow control switched ECAL off after a few days.
- One new PCB was not connected
  - (was considered to be responsible for high leakage currents.)
- Two PCBs connected to broken FEs.

Due to these problems: data of limited use!



# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0V$ .
    - mostly pedestal data.
- Leakage current raised above threshold for  $\sim 1$  PCB (which?)
  - slow control switched ECAL off after a few days.
- One new PCB was not connected  
(was considered to be responsible for high leakage currents.)
- Two PCBs connected to broken FEs.

Due to these problems: data of limited use!

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0\text{ V}$ .
    - mostly pedestal data.
- Leakage current raised above threshold for  $\sim 1$  PCB (which?)
  - slow control switched ECAL off after a few days.
- One new PCB was not connected
  - (was considered to be responsible for high leakage currents.)
- Two PCBs connected to broken FEs.

Due to these problems: data of limited use!

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0V$ .
    - mostly pedestal data.
- Leakage current raised above threshold for  $\sim 1$  PCB (which?)
  - slow control switched ECAL off after a few days.
- One new PCB was not connected
  - (was considered to be responsible for high leakage currents.)
- Two PCBs connected to broken FEs.


Due to these problems: data of limited use!

# Problems - January 2006

- ECAL connected to prototype CRCs.
- DAQ was not ready for combined test.
  - Trigger distribution problem
    - signal in one or the other half of the detector.
  - bugs/features in DAQ control program
    - calibration chip was on but with  $\sim 0V$ .
    - mostly pedestal data.
- Leakage current raised above threshold for  $\sim 1$  PCB (which?)
  - slow control switched ECAL off after a few days.
- One new PCB was not connected
  - (was considered to be responsible for high leakage currents.)
- Two PCBs connected to broken FEs.


**Due to these problems: data of limited use!**

# Pedestals – Cosmics 12/2005 - 01/2006




one readout chip, 5 events per second

# Noise – Cosmics 12/2005 - 01/2006





Noise of old and new cosmics runs.  
(December 2004/January 2005 and December 2005)

# Mip Signal



# Mip MPV Shift





## Problems:

- The regulator boards were noise sources. (→Removed)
- PCB controlling was sub-optimal. (→Read exactly 18 samples/chip.)
- One cable introduced noise.
- Some contacts were bad: cable – PCB / cable – Crc.

## Problems:

- The regulator boards were noise sources. (→Removed)
- PCB controlling was sub-optimal. (→Read exactly 18 samples/chip.)
- One cable introduced noise. (→Replaced.)
- Some contacts were bad: cable – PCB / cable – Crc.

## Problems:

- The regulator boards were noise sources. (→Removed)
- PCB controlling was sub-optimal. (→Read exactly 18 samples/chip.)
- One cable introduced noise. (→Replaced.)
- Some contacts were bad: cable – PCB / cable – Crc. (→Reconnected.)


## Problems:

- The regulator boards were noise sources. (→Removed)
- PCB controlling was sub-optimal. (→Read exactly 18 samples/chip.)
- One cable introduced noise. (→Replaced.)
- Some contacts were bad: cable – PCB / cable – Crc. (→Reconnected.)

## Problems:


- The regulator boards were noise sources. (→Removed)
- PCB controlling was sub-optimal. (→Read exactly 18 samples/chip.)
- One cable introduced noise. (→Replaced.)
- Some contacts were bad: cable – PCB / cable – Crc. (→Reconnected.)

# Pedestals – Cosmics February 2006




one readout chip, ADC minus mean of first 20 events.

# Noise – Cosmics February 2006












Noise of old, previous and new cosmics runs.  
(December 2004, January 2006 and February 2006)

# Noise – Cosmics February 2006




Noise of old, previous and new cosmics runs.  
(December 2004, January 2006 and February 2006)





# Signal – Cosmics February 2006



Gaussian fit to peak position.

(Maximum is shifted by Noise from Landau  $MPV \pm 2ADC$ )

# Summary

- Sub optimal PCB control → unstable pedestals.  
Solved.
- Noise back to normal level.  
Due to removal of regulators, correct PCB control.
- Gain compatible to Cosmics 2004?.

# Summary

- Sub optimal PCB control → unstable pedestals.  
Solved.
- Noise back to normal level.  
Due to removal of regulators, correct PCB control.
- Gain compatible to Cosmics 2004?.

# Summary

- Sub optimal PCB control → unstable pedestals.  
Solved.
- Noise back to normal level.  
Due to removal of regulators, correct PCB control.
- Gain compatible to Cosmics 2004?.

FIN

# Mip Selection

- $S/N > 3.5$   
(to take higher noise into account.)
- $3 \leq \text{hits} \leq 10$  with  $< 20$  mm distance.
- $\sum_i S_i > 120\text{ADC}$  .
- $\chi^2/n.d.f. < 1.8$  of line fit through hits.